CONCIDENTIAL

RKE TOUR LE

8 MAR 1965

				O minicipal		
	A STANCE A STORY					
25X1A2d1	MEMORANDUM FOR THE RECORD					
	SUBJECT:	Project Diesel Electr	Checkout and Testing ic Sets	of 3-335 KW	25X1A9a	
25X1A5a1	REFS :	(a) Memo from		dated \mathcal{Q}		
			ICS/PD from C/UEB/RE	CD dated		
			ICS/OD from C/UEB/RE	CD dated		
		20 Augus (d) Memo from	to Co	ntracting	25X1A5a1	
		Officer (e) Memo from	dated 27 October 196 to Co	ի ntracting	25X1A5a1	
		Officer of	dated 4 December 196	4	25X1A5a1	
	•	(f) Memo from 6 August		IIIcer dated	ZUNIMUAI	
25X1A5a1	1.		was giv	en a contract in		
25X1A2d1		1964, to checkout ion system on Pro	t and test the power	generating and representative	25X1A5a1	
	started t		testing on 7 December			
		•	· been concerned about	the length of		
	time take	n by the repr	resentative in getti	ng these deficienc	ie 25 X1 A5 a1	
C	corrected	•			25X1A5a1	
2 DC/12 Seen			nterviewed in the off the following inferen		25X1A5a1	
LO KEC			I fortri one monucetted :	200	25X1A5a1	
C/VCO	matu	-	services requested provided for	test and		
3 C CE/W/ 25X10	and the second second	kout when he star	rted to work on 7 Dec	cember 1964.		
y due wy			tallation team consider to have been			
1 to 4-	supe	rvised.				
on Place 7	allow w	from france 10	to be rure to your request.	hat	25X1A5a1	
FIL	ts Oly.	natification	You request.	51 5 3	1 5 9 8	
CRIE COMP	OF 2-8	2 BY 006/89		OL 5	1,000	
	ed For Rei		4-PDP78-056014000300	ELANG Gam Quiomatic		
LIUSI CAC NEX	I KEN GOLG	AUTH HR 10-2	OUMINETALIAL	downgrading and declassification		

Approved For Release 2001/07/30 : CIA-RDF 8 0460 14000B00140003-0

25X1A2g	SUBJECT: - Checkout and Testing of 3-335 KW Diesel Electric Sets				
	c. The electric generator sets were not properly installed and some work was done over. Some of the modified work, by is not in accordance with good installation practice but is acceptable, considering the circumstances.	25X1A5a1			
	d. The high-potential test of the power feeders was not contemplated and consumed a considerable amount of time.				
	e. The faulty operation of the tachometers was caused by a mistake in installation.	25X1A5a1			
	f. The malfunction of the reverse power relays appear to have been caused by someone in the field making adjustments and not understanding the function of these relays.				
	g. does not appear to have the required knowledge or skill that was necessary for this checkout and, therefore, the time period was greatly extended.	25X1A5a1			
25X1A9a	agreed to investigate the difficulty encountered with the reverse power relays and to supply new relays. If these cannot be installed by our operator, he will make arrangements to have them installed and tested.				
5X1A9a	agreed that the invoice for work would be adjusted to compensate for caused failures and delay in the testing and checking out.	k25X1A5a1 y 8 5X1A5a1			
	6. It appears that all deficiencies except two have been corrected and the power plant is in an operating condition.				
	a. An exhaust manifold, that was cracked, should be installed. A new one supplied by the state of the site but did not arrive in time for installation by	25X1A5a1 25X1A5a1			

b. The reverse power relays are to be replaced

and made operational.

Approved For Release 2001/07/30 : CIA-RDP 8-0560 A000300 140003-0

25X1A2q

SUBJECT:

 Checkout and Testing of 3-335 KW Diesel Electric Sets

7. It is recommended that these electric sets be operated for at least two hours daily, under load available, until they are placed in service.

25X1A5a1

- 25X1A5a1 The attached report, ref. (a) above, from the field- engineer who visited the site in January 1965 is for your information and guidance. The units that he inspected and made recommendations are similar to the ones in our power house (16V-71). Your attention is directed to the last paragraph of this report. "For maximum engine life, these sets should not be operated continuously in excess of 280 KW output." It appears that the 335 KW rating on these engines is marginal and any attempt to run these engines continuously at 335 KW will increase the maintenance and operational failures.
- 9. A review of the above referenced memos discloses that there is considerable confusion as to whether the engines as installed were provided with piston rings of the latest approved type. The reason that this information is necessary is because this engine (16V-71) has been experiencing operating difficulties which causes excessive fire ring breakage and abnormal ring face 25X1A5a1 wear. (See reference (a) above). should be notified by the contracting officer that these deficiencies will be corrected if they develop. There seems to be a difference of opinion between as to whether our engines are equipped with the new ring sets. (See references (d), (e), and (f) above).

25X1A5a1

10. It is requested that the Contractor be formally 25X1A5a1 notified that he will be expected to replace the ring sets in our diesel sets with the latest type rings supplied by the manufacturer if our engines develop the type of troubles that have arisen in this engine on other installations.

> X1A9a UEB/RECD

Attachments: (Refs a-f)

Distribution:

Orig. - OL/RECD

1 - OC/E w/atts.

1 - OC/P w/atts.

1 - EE Div. w/atts. 1 - OL/RECD/Project (Official)

1 - OL/PD/GFB/IDPS w/atts.

1 - OL/RECD/UEB/Chrono w/atts.

25X1A9a

OL/RECD/UEB, cb/3023 (8 March 1965)

MUSSING PAGE

Approved For Release 2001/07/30 : CIA-RDP78-05601A000300140003-0

ORIGINAL DOCUMENT MISSING PAGE(S):

ATTACHMENT